## **REMARKS**

### **Summary of the Office Action**

Claims 1, 3-9, 11-19, 22-24, and 27 stand rejected under 35 U.S.C. §103(a) as being unpatentable over Salisbury (US 5,303,074) in view of Henley (US 5,459,410).

Claims 21 and 26 stand rejected under 35 U.S.C. §103(a) as being unpatentable over Salisbury in view of Henley and Baum et al. (US 5,407,710).

Claims 9-16 and 27 stand rejected under 35 U.S.C. § 112, first paragraph.

The Amendment filed on March 22, 2004 is objected to under 35 U.S.C. § 132.

# **Summary of the Response to the Office Action**

Applicant has canceled claims 11, 13, 15, and 27, and amended claims 9 and 12 to further define the invention. Accordingly, claims 1, 3-9, 12, 14, 16-19, 21-24, and 26 are currently pending.

#### Objection Under 35 U.S.C. § 132

The Amendment filed on March 22, 2004 is objected to under 35 U.S.C. § 132, for allegedly introducing new matter. Accordingly, Applicant has amended claim 9 in accordance with the Examiner's comments. Thus, Applicant respectfully submits that claim 9, as currently amended, removes the ambiguities included in the Amendment filed on March 22, 2004, and respectfully requests that the objection be withdrawn.

### Rejection Under 35 U.S.C. § 112

Claims 9-16 and 27 stand rejected under 35 U.S.C. § 112, first paragraph, as allegedly failing to comply with the written description requirement. Accordingly, Applicant has amended claim 9 in accordance with the Examiner's comments and has canceled claim 27.

Thus, Applicant respectfully submits that claims 9-16 comply with the requirements of 35 U.S.C. § 112, first paragraph, and respectfully request that the rejection be withdrawn.

### Claim Rejections Under 35 U.S.C. §103(a)

Claims 1, 3-9, 11-19, and 22-24 stand rejected under 35 U.S.C. §103(a) as being unpatentable over <u>Salisbury</u> (US 5,303,074) in view of <u>Henley</u> (US 5,459,410), and claims 21 and 26 stand rejected under 35 U.S.C. §103(a) as being unpatentable over <u>Salisbury</u> in view of <u>Henley</u> and <u>Baum et al.</u> (US 5,407,710). Applicant respectfully traverses these rejections for at least the following reasons.

Independent claim 1 recites a repair structure for a liquid crystal display including, in part, "a repair pattern electrically isolated from the second segment and electrically connecting the first segment with the third segment of the data line, wherein the repair pattern bypasses to pixel electrodes adjacent to the data line and has a portion overlapping the pixel electrodes." Independent claim 9, as amended, recites a repair structure for a liquid crystal display including, in part, "a scan line crossing the data line and having first, second, and third segments, wherein the second segment is electrically isolated from the first and third segments by an insulating material and is located at a portion where the scan line and the data line overlap." Similarly, independent claim 17 recites a method of repairing a liquid crystal display including, in part, steps of "electrically isolating a portion of the data lines that are short circuited with the scan lines where the data lines and scan lines are overlapped, thereby forming first, second, and third segments of the data lines, wherein the isolated portion is the second segment," and "forming an insulating material to fill portions between the first and second segments of the data lines and between the second and third segments of the data lines." Furthermore, independent claim 22 recites a method of repairing a liquid crystal

display including, in part, steps of "electrically isolating a portion of the scan lines that are short circuited with the data lines where the data lines and scan lines are overlapped, thereby forming first, second, and third segments of the scan lines, wherein the isolated portion is the second segment," and "forming an insulating material to fill portions between the first and second segments of the scan lines and between the second and third segments of the scan lines."

The Office Action admits that "Salisbury does not expressly disclose that the repair pattern bypasses to pixel electrodes adjacent to the data line and has a portion overlapping the pixel electrodes," and "forming an insulating material to fill the portions between the second segment and the first segment of the data lines (or the scan lines) and between the second segment and the third segment of the data lines (or the scan lines)." Thus, the Office Action relies upon Henley for allegedly teaching a conductive bridge 88 such that "when forming the conductive bridge, the repair pattern must have a portion of the conductive bridge must have a portion overlapping the pixel electrodes adjacent to the data line" and "the conductive bridge must have a portion overlapping the pixel electrodes" (emphasis added). In addition, the Office Action relies upon Henley for apparently asserting that "[b]ecause the gate line (scan line) and the data line form the pixel region, as shown in Figs. 6 and 14, and the repair pattern is a conductive bridge across the pixel region as shown in Fig. 12." Furthermore, the Office Action asserts that "Henley indicates (col.2, lines 15-18) such repair structure improving the production yields, especially, for assembling high density active matrix LCD panels."

As a result, the Office Action alleges that it would have been "obvious to those skilled in the art at the time the invention was made to arrange a repair pattern as claimed in claims 1, 9 and 27 for improving the production yields of the high density active matrix LCD display."

Attorney Docket No.: 041501-5423

Application No.: 09/843,781

Page 11

However, Applicant respectfully asserts that the Office Action's alleged motivation to modify Salisbury (i.e., arranging a repair pattern for improving the production yields of the high density active matrix LCD display) is neither taught nor suggested anywhere in Henley. As clearly shown in FIGs. 12a-12c and discussed at col. 11, line 65 to col. 12, line 6 of Henley, the conductive bridge 88 is formed to contact areas 84 and 86 without shorting to data line 13. However, Applicant respectfully asserts that Henley is silent with respect to overlapping adjacent pixel electrodes. Furthermore, Applicant respectfully asserts that FIGs. 6 and 14 of Henley are merely schematic circuit diagrams that neither teach nor suggest "the repair pattern is a conductive bridge across the pixel region," as alleged by the Final Office Action. Accordingly, Applicant respectfully asserts that Henley is completely silent with respect to the repair pattern bypasses to pixel electrodes adjacent to the data line and "has a portion overlapping the pixel electrodes," as recited by independent claim 1, and hence dependent claims 3-8.

The Office Action further admits that <u>Salisbury</u> does not expressly disclose "forming an insulating material to fill the portions between the second segment and the first segment of the data lines (or the scan lines) and between the second segment and the third segment of the data lines (or the scan lines)." In addition, the Office Action apparently relies upon reasoning that "[a]though Salisbury does not expressly discloses [sic] forming an insulating material to fill the portions between the second segment and the first segments of the data lines (or scan lines) and between the second segment and the third segments of the data lines (or scan lines), but to insulate the two conductive segments using insulating material that is the same principle as to insulate the repair lines and the transmission lines as Salisbury disclosed (col.7, line 65 – col.8, line 3) that using <u>silicon oxide or silicon nitride</u>, i.e., <u>insulating material</u>, to

Attorney Docket No.: 041501-5423 Application No.: 09/843,781

Page 12

to insulate the two conductive lines, and this is a conventional technique filling an insulating material between the two conductive segments in order to insulate the two conductive segments, because the insulating material has a reliable insulating property."

As a result, the Office Action alleges that it would have been "obvious to those skilled in the art at the time the invention was made to fill an insulating material into the portions between the segments of the data lines or scan lines as claimed in claims 17 and 20 in order to obtain a reliable insulation between the conductive segments."

However, Applicant respectfully asserts that the Office Action's alleged reasoning (i.e., motivation) to modify Salisbury (i.e., electrically insulating adjacent data or scan line segments) is neither taught nor suggested anywhere in Salisbury. As discussed at col. 6, lines 36-45 of Salisbury, "the associated repair line allows the two lines to be electrically coupled without the device needing to be disassembled to make the coupling." Moreover, Salisbury discloses (col. 3, lines 27-30) that "[i]t is another object of the present invention to provide a thin film electronic device structure that readily provides for repair of the device after it has been fabricated" (emphasis added). Accordingly, the device disclosed by Salisbury is designed to be repaired without any additional fabrication processing, i.e., deposition of conductive/insulative materials. Thus, Applicant respectfully asserts that the Office Actions' alleged reasoning is directly contrary to the disclosure of Salisbury, and as such, one of ordinary skill in the art would not re-process the device of Salisbury to deposit insulating material within the severence points 160A and 160B in FIG. 2B of Salisbury.

Applicant further asserts that the Office Action does not rely on <u>Baum et al.</u> to remedy the deficiencies of <u>Salisbury</u> and/or <u>Henley</u>. Moreover, Applicant respectfully asserts that <u>Baum et al.</u> cannot remedy the deficiencies of <u>Salisbury</u> and/or <u>Henley</u>.

Accordingly, Applicant respectfully notes that MPEP 2143.01 instructs that "[o]bviousness can only be established by combining or modifying the teachings of the prior art to produce the claimed invention, where there is some teaching, suggestion or motivation to do so found either explicitly or implicitly in the references themselves or in the knowledge generally available to one of ordinary skill in the art." Moreover, MPEP 2143 instructs that "[t]he mere fact that references can be combined or modified does not render the resultant combination obvious unless that prior art also suggests the desirability of the combination. *In re Mills*, 916 F.2d 680, 16 USPQ2d 1430 (Fed. Cir. 1990)."

Thus, Applicant respectfully asserts that the Office Action has not provided any motivation for one of ordinary skill in the art to modify the teachings of <u>Salisbury</u> with the teachings of <u>Henley</u> and/or <u>Baum et al.</u> to achieve the invention of independent claim 1, 9, 17, and 22, and hence dependent claims 3-8, 12, 14, 16, 18, 19, 21, 23, 24, and 26.

Since the Office Action fails to meet the requirements for establishing a *prima facie* case of obviousness as to independent claims 1, 9, 17, and 22, claims 1, 9, 17, and 22 are not obvious. Further, since claims 3-8, 12, 14, 16, 18, 19, 21, 23, 24, and 26 depend from claims 1, 9, 17, and 22, and incorporate all the features of claims 1, 9, 17, and 22, claims 3-8, 12, 14, 16, 18, 19, 21, 23, 24, and 26 are not obvious at least for at least the above reasons for which independent claims 1, 9, 17, and 22 are not obvious. Thus, Applicant respectfully requests that all rejections under 35 U.S.C. § 103(a) be withdrawn.

Attorney Docket No.: 041501-5423

Application No.: 09/843,781

Page 14

# **CONCLUSION**

In view of the foregoing, Applicant respectfully requests the Examiner's reconsideration and reexamination of the application and the timely allowance of the pending claims. Should there remain any questions or comments regarding this response or the application in general, the Examiner is urged to contact the undersigned at the number listed below.

If there are any fees due in connection with the filing of this response, please charge the fees to our Deposit Account No. 50-0310. If a fee is required for an extension of time under 37 C.F.R. § 1.136 not accounted for above, such extension is requested and the fee should also be charged to our Deposit Account.

Respectfully submitted,

MORGAN, LEWIS & BOCKIUS LLP

By: \_

David B. Hardy Reg. No. 47,362

Date: June 23, 2004

**Customer No.: 009629** 

MORGAN, LEWIS & BOCKIUS LLP

1111 Pennsylvania Avenue, N.W.

Washington, D.C. 20004

Telephone: 202.739.3000

Facsimile: 202.739.3001